


Edificio administrativo del Santuario de Izumo



Kenta Mabuchi / CC BY-SA 2.0

This file is licensed under the Creative Commons Attribution-ShareAlike 2.0 Generic

URL: <https://creativecommons.org/licenses/by-sa/2.0/>



Kenta Mabuchi / CC BY-SA 2.0

This file is licensed under the Creative Commons Attribution-ShareAlike 2.0 Generic

URL: <https://creativecommons.org/licenses/by-sa/2.0/>



Kenta Mabuchi / CC BY-SA 2.0

This file is licensed under the Creative Commons Attribution-ShareAlike 2.0 Generic

URL: <https://creativecommons.org/licenses/by-sa/2.0/>



Kenta Mabuchi / CC BY-SA 2.0

This file is licensed under the Creative Commons Attribution-ShareAlike 2.0 Generic



Kenta Mabuchi / CC BY-SA 2.0

This file is licensed under the Creative Commons Attribution-ShareAlike 2.0 Generic

URL: <https://creativecommons.org/licenses/by-sa/2.0/>





Kenta Mabuchi / CC BY-SA 2.0

This file is licensed under the Creative Commons Attribution-ShareAlike 2.0 Generic

URL: <https://creativecommons.org/licenses/by-sa/2.0/>



Kenta Mabuchi / CC BY-SA 2.0

This file is licensed under the Creative Commons Attribution-ShareAlike 2.0 Generic

URL: <https://creativecommons.org/licenses/by-sa/2.0/>



Kenta Mabuchi / CC BY-SA 2.0

This file is licensed under the Creative Commons Attribution-ShareAlike 2.0 Generic



Bigjap / CC BY 1.0

This file is licensed under the Creative Commons Attribution 1.0 Generic

Autor/es:

Kiyonori Kikutake

Colaborador/es:

Localización:

Izumo , Prefectura de Shimane , Japón

Dirección:

195 Taishach? Kizukihigashi Izumo-shi, Shimane-ken 699-0701 Japón

Fecha:

1961 - 1963

Estado:

Demolido* !

Visitable:

no

Construido:

sí

Descripción

Construcción: junio 1961 - mayo 1963 / Tras el incendio de 1953, donde ardieron el antiguo edificio de oficinas y el propio edificio del santuario exterior (Haiden) y dada la importancia de este emplazamiento, se plantea inmediatamente la sustitución del primero y la reconstrucción del segundo (finalizado en 1959 según proyecto de Toshio Fukuyama) / En el segundo semestre de 2016 ,el edificio de oficinas es demolido tras, al parecer, repetidos problemas con filtraciones de agua.

Página web:

<https://c20society.org.uk/botm/the-izumo-grand-shrine-administrative-building-japan/>

Añadido por: David Delgado

Editado por: David Delgado